

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
TRANSMITTAL SHEET
WW-ASB-61-001
Hub Inspection

April 21, 2025

This page transmits a revision to Alert Service Bulletin WW-ASB-61-001.

- Original Issue, dated Apr 07/25
- Revision 1, dated Apr 21/25

Propeller assemblies that have previously complied with an earlier version of this Alert Service Bulletin are affected.

Changes are shown by a change bar in the left margin of the revised pages.

Revision 1 is issued to change the following in the Alert Service Bulletin:

- Revised the "Description" section
- Added the "Appendix" section

This Alert Service Bulletin is reissued in its entirety.

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
TRANSMITTAL SHEET
WW-ASB-61-001
Hub Inspection

(Blank Page)

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

1. Planning Information

A. Effectivity

- (1) All Whirlwind Propeller GA-200L-() models are affected by this Alert Service Bulletin.

WARNING: DO NOT USE OBSOLETE OR OUTDATED INFORMATION. PERFORM ALL INSPECTIONS OR WORK IN ACCORDANCE WITH THE MOST RECENT REVISION OF THIS ALERT SERVICE BULLETIN. INFORMATION CONTAINED IN THIS ALERT SERVICE BULLETIN MAY BE SIGNIFICANTLY CHANGED FROM EARLIER REVISIONS. FAILURE TO COMPLY WITH THIS ALERT SERVICE BULLETIN OR THE USE OF OBSOLETE INFORMATION MAY CREATE AN UNSAFE CONDITION THAT MAY RESULT IN DEATH, SERIOUS BODILY INJURY, AND/OR SUBSTANTIAL PROPERTY DAMAGE. REFER TO THE ALERT SERVICE BULLETIN INDEX FOR THE MOST RECENT REVISION LEVEL OF THIS ALERT SERVICE BULLETIN.

B. Concurrent Requirements

- (1) Additional service documents may apply to the components/propellers affected by this Alert Service Bulletin. Compliance with additional service documents may be necessary in conjunction with the completion of the Accomplishment Instructions in this Alert Service Bulletin.

C. Reason

- (1) Whirlwind Propeller has received reports of cracking around the bolt holes in the hubs on affected propellers.
- (2) Whirlwind Propeller has received reports of broken hub clamping bolts on affected propellers.
- (3) Whirlwind Propeller has received reports of torque loss on the aft mounting bolts on affected propellers.

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

D. Description

- (1) This Alert Service Bulletin provides Instructions for Continued Airworthiness (ICA).
- (2) This Alert Service Bulletin provides instructions for inspecting the hub and the hub hardware on affected propellers.
 - (a) Refer to the Appendix section of this Alert Service Bulletin for information about discounted pricing for replacement hubs.
- (3) This Alert Service Bulletin provides instructions for inspecting the spinner backing plate on affected propellers.
- (4) This Alert Service Bulletin requires recurring inspections of the hub on affected propellers.
- (5) This Alert Service Bulletin requires recurring replacement of the hub hardware on affected propellers.

E. Compliance

- (1) Initial Inspection
 - (a) Before further flight, examine the hub on the affected propeller in accordance with the "Hub Inspection" procedure in the Accomplishment Instructions section of this Alert Service Bulletin.
 - 1 Spinner Backing Plate Inspection
 - a When the hub is removed during the Initial Hub Inspection, examine the spinner backing plate in accordance with the "Spinner Backing Plate Inspection" in the Accomplishment Instructions section of this Alert Service Bulletin.
- (2) Recurring Inspections
 - (a) At recurring intervals of 25 flight-hours or 6 months, whichever occurs first, examine the hub on the affected propeller in accordance with the "Hub Inspection" procedure in the Accomplishment Instructions section of this Alert Service Bulletin.

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

(3) Recurring Hardware Replacement

- (a) After every eight "torque-up events" on the hub clamping/mounting bolts, replace all of the washers in accordance with the section, "Washer Replacement" in the Accomplishment Instructions section of this Alert Service Bulletin.

NOTE: Any occurrence that requires the hub clamping/mounting bolts to be loosened/tightened is considered a "torque-up event". Examples include: Torque checks, blade pitch adjustments, inspections, etc.

- (b) At recurring intervals of 200 flight-hours or 24 months, whichever occurs first, replace the hub mounting hardware on the affected propeller in accordance with the section, "Hub Hardware Replacement" in the Accomplishment Instructions section of this Alert Service Bulletin.

F. Approval


- (1) This technical document is approved by Whirlwind Propeller.

CAUTION: DO NOT USE OBSOLETE OR OUTDATED INFORMATION.
PERFORM ALL INSPECTIONS OR WORK IN ACCORDANCE WITH
THE MOST RECENT REVISION OF A DOCUMENT.

G. References

- (1) Applicable Whirlwind Propeller Owner's Manual
- available on the Whirlwind Propeller website at www.whirlwindpropellers.com


WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection




TPI-MB-0778

Hub Clamping/Mounting Bolts
Figure 1

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection



CAUTION: IN FIELD REPORTS, HUB CRACKING HAS OCCURED ON SURFACES AROUND THE BOLT HOLES. EXAMINE THE SHADED AREAS CLOSELY.



TPI-MB-0779

Hub Inspection
Figure 2

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

2. Accomplishment Instructions

A. Hub Inspection

- (1) Remove the spinner dome in accordance with the applicable Whirlwind Propeller Owner's Manual.
- (2) Using a marker, torque seal, or equivalent, make marks to indicate the pitch location of the blades.

NOTE: Marking the pitch location will assist with reassembly. Whirlwind recommends multiple marks per blade to add precision.

- (3) Remove the hub clamping/mounting hardware in accordance with Figure 1 and the following steps:
 - (a) Remove four clamping bolts/lockwashers, and four forward mounting bolts/lockwashers from the hub.
 - (b) Remove the forward hub half.
 - (c) Remove the blade assemblies.
 - (d) Remove two aft mounting bolts and washers (lock/flat).
 - (e) Remove the aft hub half from the aircraft.
- (4) Examine the bolts and washers for cracks or other damage.
 - (a) Discard any cracked, damaged, or excessively worn bolts/washers.
 - 1 Contact Whirlwind Propeller for information about replacement hardware.

CAUTION: IN FIELD REPORTS, HUB CRACKING HAS OCCURED ON SURFACES AROUND THE BOLT HOLES. EXAMINE THESE AREAS CLOSELY.

ATTENTION: PENETRANT INSPECTION CAN BE USED IF A HAIRLINE CRACK IS SUSPECTED.

- (5) Carefully examine all hub surfaces for cracks, fretting, or other damage. Refer to Figure 2.
 - (a) If no cracks, fretting, or other damage is found, go to Step (6).
 - (b) If cracks, fretting, or other damage is found, retire the damaged hub.
 - 1 A new or serviceable hub must be installed before further flight.
 - 2 Contact Whirlwind Propeller to report the cracked/damaged hub.

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

- (6) Perform the "Spinner Backing Plate Inspection" procedure in this section.
- (7) Install the aft hub half onto the aircraft.
 - (a) Torque the two mounting bolts in accordance with the applicable Whirlwind Propeller Owner's Manual.
- (8) Install the blades and the forward hub half, then set the blade pitch in accordance with the applicable Whirlwind Propeller Owner's Manual.
 - (a) Torque the four clamping bolts and four forward mounting bolts in accordance with the applicable Whirlwind Propeller Owner's Manual.

B. Spinner Backing Plate Inspection

CAUTION: PAINT IS NOT PERMITTED ON THE HUB/ENGINE MOUNTING SURFACES OF THE SPINNER BACKING PLATE.

- (1) Examine both sides of the spinner backing plate for paint on the mounting surfaces (hub/engine). Refer to Figure 3.
 - (a) If the mounting surface is painted, remove the paint in accordance with the "Paint Removal" procedure in this section.
 - 1 After removing the paint from the mounting surface(s), reinstall the spinner backing plate.
 - (b) If the mounting surfaces are not painted, reinstall the spinner backing plate.


WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

C. Paint Removal

- (1) Locate the diameter of the hub/engine mounting surface.
- (2) Mark the paint removal area at least 1/2 inch larger than the diameter of the mounting surface as shown in Figure 3.

CAUTION: REMOVE ONLY THE PAINT LAYER WHEN SANDING.

- (3) Using 220 grit sandpaper or equivalent, remove the paint in the marked area.



Paint Removal
Figure 3

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

D. Washer Replacement

NOTE: Refer to Figure 1 for the location/type of bolts and washers.

- (1) Remove the all of the hub clamping/mounting bolts and washers.
 - (a) Discard all of the washers.
- (2) Install new washers on the hub clamping/mounting bolts.
 - (a) Install (and torque) the hub clamping/mounting bolts and washers in accordance with the applicable Whirlwind Propeller Owner's Manual.

E. Hub Hardware Replacement

NOTE: Refer to Figure 1 for the location/type of bolts and washers.

- (1) Remove and discard all of the hub clamping/mounting bolts and washers.
- (2) Install new hub clamping/mounting bolts and washers.
 - (a) Install (and torque) the hub clamping/mounting bolts and washers in accordance with the applicable Whirlwind Propeller Owner's Manual.

3. Contact Information

Whirlwind Propeller
Attn.: Product Support Department
One Propeller Place
Piqua, Ohio 45356-2634 USA
Phone: (001) 937.778.4379
Fax: (001) 937.778.4391
E-mail: techsupport@whirlwindpropellers.com

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN
WW-ASB-61-001
Hub Inspection

(Blank Page)

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN APPENDIX
WW-ASB-61-001
Hub Inspection

1. Discounted Pricing Information

A. Eligibility

- (1) All Whirlwind Propeller GA-200L-() models are eligible for discounted pricing on replacement hub units.

B. Price Discount/Duration

- (1) Whirlwind Propeller is offering a 25% discount when a replacement hub is purchased for a propeller affected by this Alert service Bulletin.
 - (a) The discount will be applied to the published list price for the applicable hub unit.
 - (b) This discount will be available for a period of one calendar year from the release date of this Alert Service Bulletin (Rev. 1).
- (2) Complete and sign the Parts Order/Compliance Form in this Appendix section, then send the completed form to Whirlwind Propeller for processing.

C. Contact Information

- (1) Fax, Email, or mail the Parts Order/Compliance Form to:

Whirlwind Propeller
Attn: Alert Service Bulletin 001 Coordinator
One Propeller Place
Piqua, OH 45356 USA
Phone: 937.778.4379
Fax: 937.778.4215 (Intl. 001.937.778.4215)
Email: techsupport@whirlwindpropellers.com

WHIRLWIND PROPELLER
ALERT SERVICE BULLETIN APPENDIX
WW-ASB-61-001
Hub Inspection

Parts Order/Compliance Form

Whirlwind Reference Number:		
Propeller Information:		
Propeller Model <i>ex. GA-200L (616, 716, or 816):</i>	Propeller S/N:	
	TSN (Time Since New):	
Aircraft Information		
Aircraft Model:	Aircraft Registration #:	
Owner Information:		
Name:		
City:	State:	
Zip/Postal Code:	Country:	
E-mail:	Phone:	
Shipping Information:		
Company:	Contact Name:	
Address:		
City:	State:	
Zip/Postal Code:	Country:	
E-mail:	Phone:	Fax:
Replacement Parts:		
Refer to the "Discounted Pricing Information" section in this Appendix for part eligibility and pricing information		
Signature:		
Repair Technician's Signature:	Date:	
Send this completed and signed form to Whirlwind Propeller Product Support Department: Fax - (001) 937.778.4215 or E-mail - techsupport@whirlwindpropellers.com		

DO NOT WRITE BELOW THIS LINE - FOR WHIRLWIND PROPELLER USE ONLY

Authorized By:

Document No. WW-ASB-61-001 Date of Issue: Apr 07/25 Revision: 1 Rev. Date: Apr 21/25