

Whirl Wind Propellers Corp

Service Memo RQ01-2010 Rev B

Issue Date: 04-12-2010

Revised Date: 12-10-2010

TO: ALL OWNERS AND OPERATORS OF WHIRL WIND RQ 72L
REPLACEMENT AIRBOAT BLADES

SUBJECT: Mandatory to discontinue use of this blade model.

BLADE MODEL: RQ72L

**SERIAL NUMBERS
AFFECTED:** ALL Serial Numbers

REASON: Possible improper fit between blade shank and certain Power Shift / Water Walker / Sensenich hubs has been found to cause cracks in the blade structure which can lead to blade failure.

ACTION REQUIRED: If you own or operate RQ 72L blades, you must discontinue use immediately. Continuing to operate the RQ 72L blade style will result in blade failure.

For additional information, please contact Whirl Wind Propellers at 619-562-3725